





317729100 VACUUM TANK ASSEMBLY INSTRUCTIONS



VACUUM TANK SOLVENT WELDING INSTRUCTIONS

Determine location and mounting (horizontal or vertical) of vacuum tank by instructions in owner's or installation manual.

Select fittings needed from those provided with tank.

IMPORTANT

- Use PVC cleaner on all solvent weld joints prior to solvent welding.
- Use PVC cement with Tetrahydrofuran for solvent weld joints.
- Follow instructions on PVC cleaner and PVC cement for maximum adhesion and safety.