

## Refrigerators Available for Replacement

### REPLACING AN OLD DOMETIC WITH A CURRENT MODEL

Model #	Height	Width	Depth	Dometic Replacement Options	Height	Width	Depth
RM24	22 3/8	19 3/8	19 7/8	RM2193	21	17 3/4	21 1/2
RM190	21 1/2	18 3/4	19 1/2	RM2193	21	17 3/4	21 1/2
RM211	22 11/16	19 5/8	17 5/8	RM2193	21	17 3/4	21 1/2
RM2150	17 1/2	17 3/4	21 1/2	RM2193	21	17 3/4	21 1/2
RM2190	21 1/2	17 3/4	20 1/2	RM2193	21	17 3/4	21 1/2
RM2191, 2193	20 7/8	17 3/4	20 7/8	RM2193	21	17 3/4	21 1/2
RM2200, 2201, 2202	22 1/4	19 1/2	18 1/4	RM2193	21	17 3/4	21 1/2
RM182B	23 1/2	17	17 1/4	NO DIRECT VENT REPLACEMENT			
RM215	27 1/2	19 3/8	18 1/2	NO DIRECT VENT REPLACEMENT			
RM2192	24 3/16	17 3/4	21 1/8	NO DIRECT VENT REPLACEMENT			
RM4223	20 15/16	19 5/8	24	CURRENT			
RM4290, 4292	29 5/8	20 5/8	20	RM2351, 2354	29 3/4	20 5/8	20
RM36	28 3/4	20 1/2	20 5/8	RM2351, RM2354	29 3/4	20 1/2	21 3/8
RM360, 361, RM2300, 2301, RM2310, 2332, 2333	29 3/4	20 1/2	21 3/8	RM2351, RM2354	29 3/4	20 1/2	21 3/8
RM45, 46, 47	31 1/4	21 7/8	23 5/8	RM2351, 2354 RM2410	29 3/4 32 7/16	20 1/2 21 13/16	21 3/8 24
RM460, 461, 2400, RM2401, 2410	32 7/16	21 13/16	24	RM2410	32 7/16	21 13/16	24
RB2195	20 7/8	18	20	NO COMPRESSOR REPLACEMENT			
RB2405	31 3/4	21 7/8	24	NO COMPRESSOR REPLACEMENT			
RM60, 66, 67	39 3/16	21 7/8	23 5/8	RM2510	40 5/16	21 13/16	24
RM660, 661, 663, RM2500, 2501, 2510	40 5/16	21 13/16	24	RM2510	40 5/16	21 13/16	24
RM3500, 3501	38 3/16	21 13/16	24	RM2510 (NOT AES)	40 5/16	21 13/16	24
RM760, 761, 763 RM2600, 2601, 2610	51 3/8	21 13/16	24	RM2620	49 1/2	21 3/4	24
RM2602, 2603, 2604 RM2607, 2611, 2612 RM2620, 3600, 3601 RM3604, 3607	49 9/16	21 7/8	24	RM2620	49 1/2	21 3/4	24
RM75, 76, 77	56 7/8	23 13/16	23 3/8	RM2820 RM2852, 2862, 3962*, NDR1062	55 3/8 59 15/16	23 5/8 23 11/16	24 24
RM100, 2802, 2803 RM2804, 2807, 2811 RM2812, 2820, 3800 RM3801, 3804, 3807	55 7/16	23 11/16	24	RM2820 RM2852, 2862, 3962*, NDR1062	55 3/8 59 15/16	23 5/8 23 11/16	24 24
RM1300, 1301, 1303 RM2800, 2801, 2810	57 1/2	23 13/16	23 3/4	RM2820 RM2852, 2862, 3962*, NDR1062	55 3/8 59 15/16	23 5/8 23 11/16	24 24
RM4801	62 13/16	23 13/16	24	RM2862, 3962*, NDR1062IM	59 15/16	23 11/16	24
RM4804	63	23 13/16	24	RM2862, 3962*, NDR1062IM	59 15/16	23 11/16	24
RM7030, 7130	57 1/8	32 3/4	24	NDR1292, NDR1292IMH	59 1/16	32 3/4	24
S520, 530 S1521, 1531, S519	43 1/4	23 1/2	24	RM2551, 2554	42 5/8	23 11/16	24
S620, 630 S1621, S1631, S619	52 5/8	23 1/2	24	RM2652, 2662, 3762	53 3/4	23 11/16	24
S820, 830 S1821, 1831, S819	59 5/8	23 1/2	24	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
RM2452, 2453	36 9/16	23 11/16	24	2451, 2454			
RM2552, 2553	42 5/8	23 11/16	24	RM2551, 2554	42 5/8	23 11/16	24
RM2652, 2662	53 3/4	23 11/16	24	CURRENT, 3762			
RM3662, 3663	53 3/4	23 11/16	24	RM2652, 2662, 3762	53 3/4	23 11/16	24
RM2852	59 15/16	23 11/16	24	CURRENT, 3962*			
RM2862	59 15/16	23 11/16	24	CURRENT, 3962*			
NDR1062	59 15/16	23 11/16	24	CURRENT			
RM3862, 3863	59 15/15	23 11/16	24	RM2852, 3962*	59 15/16	23 11/16	24
RM3863, 4872, 4873	59 15/16	23 11/16	24	RM2852, RM2862, NDR1062, 3962*	59 15/16	23 11/16	24
RM7732, 7832	59 1/16	32 11/16	24	NDR1292, NDR1292IMH	59 1/16	32 3/4	24
RM1272, 1282 NDR1272, 1282	59 1/16	36 1/2	24	NDR1292	59 1/16	32 3/4	24
NDR1292	59 1/16	32 11/16	24	CURRENT			
NDR1492	59 1/16	36 1/2	24	NDA1402	63 11/64	32	26 1/16
RM3762	53 3/4	23 11/16	24	CURRENT			
RM3962	62 61/64	23 11/16	24	CURRENT			
RM1350	63 3/16	32 3/4	26 1/16	CURRENT			
NDR1402	63 3/16	32 3/4	26 1/16	CURRENT, RM1350	63 3/16	32 3/4	26 1/16

\*RM3962 approximately 3 inches higher than 2852, 2862.

## First and Foremost in RV Refrigeration

### REPLACING A NORCOLD WITH A DOMETIC

Model #	Height	Width	Depth	Dometic Replacement Options	Height	Width	Depth
322, 333	20 5/8	17 1/2	21 1/4	RM2193	21	17 3/4	21 1/2
442, 443	30 7/8	23 1/2	24	RM2351, 2354	29 3/4	20 1/2	21 3/8
				RM2410	32 7/16	21 13/16	24
774, 874	33 1/8	22	21 3/4	RM2410	32 7/16	21 13/16	24
452, 453	42 1/4	23 5/8	24	RM2551, 2554	42 5/8	23 11/16	24
652, 653	42 1/2	23 5/8	24	RM2551, 2554	42 5/8	23 11/16	24
775	40 1/8	22	21 1/2	RM2510	40 5/16	21 13/16	24
875	40	22	21 3/4	RM2510	40 5/16	21 13/16	24
6052, 6053	43 1/4	23 1/2	24	RM2551, 2554	42 5/8	23 11/16	24
838	51 7/8	23 15/16	23 1/2	RM2652, 2662, 3762	53 3/4	23 11/16	24
462, 463, 662, 663, 641	52 7/8	23 1/2	24	RM2652, 2662, 3762	53 3/4	23 11/16	24
876	52 1/8	24	24	RM2652, 2662, 3762	53 3/4	23 11/16	24
8662	52 1/2	23 5/8	24	RM2652, 2662, 3762	53 3/4	23 11/16	24
8310	58 7/8	23 15/16	23 1/2	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
878	59	24	24	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
482, 483, 682, 683, 841	59 7/8	23 1/2	24	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
8010	59	23 7/8	24	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
8682	59 1/2	23 5/8	24	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
N260/N260.3	21	19 3/8	24	RM2193	21	17 3/4	21 1/2
N300/N300.3	29 3/4	20 1/2	21 3/8	RM2351	29 3/4	20 1/2	21 3/8
				RM2354	42 5/8	23 11/16	24
N400/N400.3	36 9/16	23 11/16	24	RM2410	32 2/16	21 13/16	24
				RM2510	40 5/16	21 13/16	24
N500/N500.3	42 5/8	23 11/16	24	RM2510	40 5/16	21 13/16	24
N510/N510.3				RM2551	42 5/8	23 11/16	24
				RM2554	42 5/8	23 11/16	24
N641/N641.3	52 7/8	29 1/2	24	RM2620	49 1/2	21 3/4	24
				RM2652, 3762	53 3/4	23 11/16	24
N841/N841.3	59 7/8	29 1/2	24	RM2820	55 3/8	23 5/8	24
				RM2852, 3962*	59 15/16	23 11/16	24
				RM2862, NDR1062	59 15/16	23 11/16	24
1200LR/LAIM	63 1/4	32 11/16	24	NDA1402	63 3/16	32 3/4	26 1/16

### REPLACING AN INSTAMATIC WITH A DOMETIC

RV-2-201	21 3/4	19 3/16	18 3/16	RM2193	21	17 3/4	21 1/2
IM-2	22 1/4	18 1/8	16 5/8	RM2193	21	17 3/4	21 1/2
RV-3-301	28 3/4	20 11/16	19 7/16	RM2351, 2354	29 3/4	20 1/2	21 3/8
IM-3	28 3/8	20 1/4	18 5/8	RM2351, 2354	29 3/4	20 1/2	21 3/8
IM-140	31 1/4	22	22 3/4	RM2410	32 7/16	21 13/16	24
IM-40	31 1/2	24	23	RM2410	32 7/16	21 13/16	24
RV-4-401	33 15/16	20 11/16	21 5/8	RM2410	32 7/16	21 13/16	24
IM-4	31	21 5/8	22 5/8	RM2410	32 7/16	21 13/16	24
RV-6-601	40 3/16	22 5/16	22 1/8	RM2510	40 5/16	21 13/16	24
IM-6	38 7/8	21 5/8	22 5/8	RM2510	40 5/16	21 13/16	24
RV-7-701	53 1/8	23 7/8	23 1/4	RM2652, 2662, 3762	53 3/4	23 11/16	24
IM-270	51 3/4	23 3/4	23 1/4	RM2652, 2662, 3762	53 3/4	23 11/16	24
IM-70	52	24	23	RM2652, 2662, 3762	53 3/4	23 11/16	24
IM-7	56 1/2	23 1/2	22 3/8	RM2820	55 3/8	23 5/8	24
IM-10	55 1/8	23 1/2	22 5/8	RM2820	55 3/8	23 5/8	24
RV-8-801	59 5/16	23 7/8	23 3/4	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24

### REPLACING A SIBIR WITH A DOMETIC

RV-104	30 5/16	23 1/2	23	RM2351, 2354	29 3/4	20 1/2	21 3/8
RV-106	34 3/8	23 1/2	23	RM2410	32 7/16	21 13/16	24
				RM2451, 2454	36 9/16	23 11/16	24
RV-240	34 1/8	23 1/2	23	RM2410	32 7/16	21 13/16	24
				RM2451, 2454	36 9/16	23 11/16	24
RV-108	54 3/8	23 1/2	23	RM2652, 2662, 3762	53 3/4	23 11/16	24
RV-270	54 1/16	23 1/2	23	RM2652, 2662, 3762	53 3/4	23 11/16	24
RV-110	64 3/8	23 1/2	23	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24
RV-280	59	23 1/2	23	RM2852, 2862, 3962*, NDR1062	59 15/16	23 11/16	24

### REPLACING A GE WITH A DOMETIC

TG-3	28 3/8	20 1/4	19 5/8	RM2351, 2354	29 3/4	20 1/2	21 3/8
TG-4	31	21 5/8	22 5/8	RM2351, 2354	29 3/4	20 1/2	21 3/8
				RM2410	32 7/16	21 13/16	24
TG-5	38 7/8	21 5/8	22 5/8	RM2410	32 7/16	21 13/16	24
				RM2510	40 5/16	21 13/16	24

\*RM3962 approximately 3 inches higher than 2852, 2862.