


→ DOMETIC

NRX0090V






12/24 V


R600a




DIMENSIONS





Absorber MDC90





NRX0090V






NRX0090V







⚠ DANGER



NOTICE





NOTICE




AIR FLOW



Insufficient air flow results in shortened lifespan and reduced cooling performance. Observe the minimum spacings when installing the refrigerator to furniture.




CONDENSATION DRAIN




DC







FIXING



FIXING



REVERSING DOOR



DOMETIC

YOUR LOCAL DEALER
dometic.com/dealer

YOUR LOCAL SUPPORT
dometic.com/contact

YOUR LOCAL SALES OFFICE
dometic.com/sales-offices

A complete list of Dometic companies, which comprise the Dometic Group, can be found in the public filings of: **DOMETIC GROUP AB** Hemvärnsgatan 15 SE-17154 Solna Sweden

4445103940 2024-06-26